



- [4101](#) - PURITAN-BENNET, O<sub>2</sub>, QUICK CONNECT X 1/8 NPT MALE
- [4201](#) - PURITAN-BENNET, AIR, QUICK CONNECT X 1/8 NPT MALE
- [4301](#) - PURITAN-BENNET, VACUUM, QUICK CONNECT X 1/8 NPT MALE
- [4401](#) - PURITAN-BENNET, N<sub>2</sub>O, QUICK CONNECT X 1/8 NPT MALE



- [4102](#) - PURITAN-BENNET, O<sub>2</sub>, QUICK CONNECT X 1/8 NPT FEMALE
- [4202](#) - PURITAN-BENNET, AIR, QUICK CONNECT X 1/8 NPT FEMALE
- [4302](#) - PURITAN-BENNET, VACUUM, QUICK CONNECT X 1/8 NPT FEMALE
- [4402](#) - PURITAN-BENNET, N<sub>2</sub>O, QUICK CONNECT X 1/8 NPT FEMALE



- [4103](#) - PURITAN-BENNET, O<sub>2</sub>, QUICK CONNECT X 1/4 NPT MALE
- [4203](#) - PURITAN-BENNET, AIR, QUICK CONNECT X 1/4 NPT MALE
- [4303](#) - PURITAN-BENNET, VACUUM, QUICK CONNECT X 1/4 NPT MALE
- [4403](#) - PURITAN-BENNET, N<sub>2</sub>O, QUICK CONNECT X 1/4 NPT MALE



- [4111](#) - PURITAN-BENNET, O2, QUICK CONNECT X HOSE BARB
- [4211](#) - PURITAN-BENNET, AIR, QUICK CONNECT X HOSE BARB
- [4311](#) - PURITAN-BENNET, VACUUM, QUICK CONNECT X HOSE BARB
- [4411](#) - PURITAN-BENNET, N2O, QUICK CONNECT X HOSE BARB



- [4105](#) - PURITAN-BENNET, O2, QUICK CONNECT X DISS MALE
- [4205](#) - PURITAN-BENNET, AIR, QUICK CONNECT X DISS MALE
- [4305](#) - PURITAN-BENNET, VACUUM, QUICK CONNECT X DISS MALE
- [4405](#) - PURITAN-BENNET, N2O, QUICK CONNECT X DISS MALE



- [4114](#) - PURITAN-BENNET, O2, QUICK CONNECT X DISS MALE W/CHECK
- [4214](#) - PURITAN-BENNET, AIR, QUICK CONNECT X DISS MALE CHECK
- [4314](#) - PURITAN-BENNET, VACUUM, QUICK CONNECT X DISS MALE W/CHECK
- [4414](#) - PURITAN-BENNET, N2O, QUICK CONNECT X DISS MALE W/CHECK



[4106](#) - PURITAN-BENNET, O2, QUICK CONNECT X DISS HEX NUT

[4206](#) - PURITAN-BENNET, AIR, QUICK CONNECT X DISS HEXNUT

[4306](#) - PURITAN-BENNET, VACUUM, QUICK CONNECT X DISS HEX NUT

[4406](#) - PURITAN-BENNET, N2O, QUICK CONNECT X DISS HEX NUT



[4108](#) - PURITAN-BENNET, O2, QUICK CONNECT X DISS HANDTIGHT

[4208](#) - PURITAN-BENNET, AIR, QUICK CONNECT X DISS HANDTIGHT

[4308](#) - PURITAN-BENNET, VACUUM, QUICK CONNECT X DISS HANDTIGHT

[4408](#) - PURITAN-BENNET, N2O, QUICK CONNECT X DISS HANDTIGHT